

## 24xx MitelMinet Software release 101.027 – 9/15/09

This is a release load.

---

### **Versions**

OTADL	221.018
Functional code	221.003
Phintl	104.028

### **New Features:**

None

### **Fixes**

- ESCWIRE-8: Svc Esc (424243): 24xx phone powering off in charger OEM (Q01924957) and OEM (Q01948875) (was WTUNA-137)
- ESCWIRE-6: Svc Esc (443322): Flash Config Err on phones manufactured in 2008 (was WTUNA-202)

### **Known Issues (bugs)**

- None.
- 

## 24xx MitelMinet software release 101.026 – 08/12/09

This is a release load.

### **Versions**

OTADL	110.081
Functional code	101.026
Phintl	104.028

### **New Features**

- Created a mirror of the flash config in an unused segment of the flash. On a flash config error, it attempts to recover the latest mirror copy, and resumes if successful.
  - Note that both the OTADL and the functional code needed this fix,

### **Fixes:**

- WTUNA-202: Svc Esc (443322): Flash Config Err on phones manufactured in 2008
-

## **24xx MitelMinet software release 101.025**

This build is the same content as designer load 201.021.

I made a release candidate load 101.024.

Then I did the designer load 201.021 for 5537 (oai callback problem).

At this point I found out load 101.024 had not yet been tested by our test team so I built this load (101.025) for them to use instead since it now has the bug 5537 fix.