

Technical Bulletin 00-08



Bulletin #: CS-00-008

Software Version: All

Access Level: Reseller

Status: Approved

Date: April 20, 2000

Product Type: PTS360

Hardware Revision: All

Originator: Matt Jerger

Approvers: John Elms, Gary Bliss

Title: Battery Chargers Flashing Red and Green after charging a Battery.

Symptoms: The LED on the battery charger will flash between red and green after it has completed its charging cycle.

Problem: This can occur with Nickel Metal Hydride (PTS360) batteries that are still within their warranty period. This condition does not indicate an equipment failure. It is due to the fact that the battery needs an additional charge time. This is likely to occur during the first charge cycle after purchasing the battery, or if the battery has been conditioned.

Note: Nickel Metal Hydride batteries do not need to be conditioned

Resolution: Remove the battery from the charger and place it back on to complete another charging cycle. If the problem continues, contact SpectraLink Customer Support.

Additional Notes:
None.

DISCLAIMER

THE INFORMATION PROVIDED IN THE SPECTRALINK TECHNICAL BULLETIN IS PROVIDED "AS IS" WITHOUT WARRANTY OF ANY KIND. NO OBLIGATION OR LIABILITY WILL ARISE OUT OF, SPECTRALINK RENDERING TECHNICAL OR OTHER ADVICE OR SERVICE IN CONNECTION HEREWITH.