

Technical Bulletin CS-02-03

Hardware Changes to Support the NEC NEAX 2000 IVS²



This technical bulletin provides detailed information on hardware changes required to support the NEC NEAX 2000 IVS²

Description

The LinkPlus digital interface is now available for the NEC NEAX 2000 IVS². New SpectraLink hardware is required to support this PBX interface. All new hardware will be labeled with an identifier of Gen II. All Gen II products will be compatible with previous products.

Link 3000

For the Link 3000, you must use either the new CPU316 or CPH316 Interface Modules. The label on the front panel of the card will indicate Gen II (see Figure 1).




Figure 1

Link 150 M3

For the Link 150 M3 system, you must use either the new SCU516/508 or SCH516/508 Master Control Units. The product label on the bottom side of the MCU will indicate Gen II (see Figure 2).




Figure 2

NetLink 150

For the NetLink 150 system, you must use either the new TGU116 or TGH116 Gateways. The product label on the bottom side of the Gateway will indicate Gen II (see Figure 3).




Figure 3

The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of, Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.