

Link 150 Model 3 Error 1,2,3

Date:	December 14, 2004	Originator:	Lisa Kvasnicka
Software Versions:	53.032	Approvers:	Wayne McAllister Gary Bliss
Hardware Revisions:	SCx5xx	Status:	Approved
Product Type:	Link 150 M3	Revision:	A
Access Level:	General		

Problem

Some multiple MCU Link 150 Model 3 systems using software version 53.032 may experience error 1,2,3 on start-up.

Description

The error is not consistent with one particular MCU in the system and may occur on a different MCU after a power cycle or on several of the MCUs. If the configuration is cleared and the system is rebooted, the problem may still occur. This error impacts the entire system since error 1,2,3 will not allow the system to boot up properly.

Resolution

This is a temporary work-around, pending a permanent fix in a future product software release. Prior to the release of this fix, the system software will need to be downgraded to version 53.028. Please contact Spectralink Customer Support at 1-800-775-5330 to arrange for a software load.

